







Winter Fuel Test Results

Learn more about our Winter Fuel Additive technology at schaefferoil.com

Ohio

December 2019





Winter Fuel Test Results


Learn more about our Winter Fuel Additive technology at schaefferoil.com

Ohio

December 2019


137 ULSW, Diesel

Shreve, OH




137 ULSW, 80:20

Shreve, OH




137 ULSW, 90:10

Shreve, OH



137 ULSW, 70:30

Shreve, OH









Winter Fuel Test Results

Learn more about our Winter Fuel Additive technology at schaefferoil.com

Ohio

December 2019









Winter Fuel Test Results

Learn more about our Winter Fuel Additive technology at schaefferoil.com

Ohio

December 2019





Winter Fuel Test Results

Learn more about our Winter Fuel Additive technology at schaefferoil.com

Ohio

December 2019

